



Home

Search

Print

Previous

Next

Disclaimer: This information is for tax assessing purposes and is not warranted

## **Parcel Identification**

0022-112.000 1656

Account 73 - Ex Charter State Code

Card 1/1

Map/Lot

40-0050-00 User Account

#### **Assessment**

\$221,400 Land \$392,500 Building Card Total \$613,900 Parcel Total \$613,900

#### **Prior Assessments**

Fiscal Year	Land Value	<b>Building Value</b>	Outbuilding Value	<b>Total Value</b>
2024	\$221,400	\$382,400	\$10,100	\$613,900
2023	\$221,400	\$382,400	\$10,100	\$613,900
2022	\$184,500	\$336,200	\$10,100	\$530,800
2021	\$184,500	\$336,200	\$10,100	\$530,800
2020	\$184,500	\$336,200	\$10,100	\$530,800

## **Location and Owner**

Location

240 ARNOLD RD

Owner

CENTRAL COVENTRY FIRE DISTRICT (TIOGUE)

Owner2

Owner3

240 ARNOLD RD Address

Address2

COVENTRY RI 02816 Address3

# **Building Information**

Design Year Built FireStns 1970

Heat

**BB** Electric

Fireplaces Rooms

0 0

**Bedrooms** 

0 2 Full Bath

Bathrooms

Above Grade Living Area

6,000 SF

# Sale Information

# **Building Sub Areas**

Sub Area

1st FLOOR

**Net Area** 

CGAR (2500)

3,500 SF

COMMERCIAL GARAGE

2,500 SF

# **Land Information**

Land Area

0.55 AC

FFL (3500)

Zoning

R-20

HRESULT: 0x6d HTTP status: 500 HTTP subStatus: 1013 HTTP reason: Internal Server Error

You are receiving this HTTP 200 response because system.webServer/iisnode/@devErrorsEnabled configuration setting is 'true'.

In addition to the log of stdout and stderr of the node.exe process, consider using debugging and ETW traces to further diagnose the problem.

The last 64k of the output generated by the node.exe process to stderr is shown below:

(node:10368) [DEP0005] DeprecationWarning: Buffer() is
(Use `node --trace-deprecation ...` to show where the w
Application has thrown an uncaught exception and is ter
Error: source is not a string
 at Object.module.exports [as parse] (\\axisfiles.aw
 at \\axisfiles.aws.axisgis.com\share\axisapi\_prod\A

Click To Open AxisGIS Maps

Fire District Neighborhood Central Coventry - (401) 825-7860

Yard	Item	(s)
, ai a		<b>\</b> -,

Description PAVING ASPHALT Quantity 1

Size 7000

Year 1970





Home

Search

Print

Previous

Next

Disclaimer: This information is for tax assessing purposes and is not warranted

#### **Parcel Identification**

0318-005.000 11492

Account 73 - Ex Charter State Code

1/1

Map/Lot

User Account 40-0010-00

#### Assessment

\$226,600 Land Building \$430,700 Card Total \$657,300 \$657,300 Parcel Total

#### **Prior Assessments**

Fiscal Year	Land Value	<b>Building Value</b>	Outbuilding Value	Total Value
2024	\$226,600	\$409,500	\$21,200	\$657,300
2023	\$226,600	\$409,500	\$21,200	\$657,300
2022	\$188,800	\$360,800	\$21,200	\$570,800
2021	\$188,800	\$360,800	\$21,200	\$570,800
2020	\$188,800	\$360,800	\$21,200	\$570,800

## **Location and Owner**

Location

2847 FLAT RIVER RD

Owner Owner2 CENTRAL COVENTRY FIRE DISTRICT

Owner3

Address

240 ARNOLD RD

Address2

COVENTRY RI 02816 Address3

# **Building Information**

Design Year Built

Heat

FireStns 1950 HW w/A/C 0

Fireplaces Rooms

**Bedrooms** 


2 Full Bath

Bathrooms Above Grade Living Area

4,592 SF

# Sale Information





# **Building Sub Areas**

Sub Area 1st FLOOR **Net Area** 

4,592 SF

# **Land Information**

Land Area

0.86 AC

Zoning

VRC

Fire District

Central Coventry - (401) 825-7860

HRESULT: 0x6d HTTP status: 500 HTTP subStatus: 1013

HTTP reason: Internal Server Error

You are receiving this HTTP 200 response because system.webServer/iisnode/@devErrorsEnabled configuration setting is 'true'.

In addition to the log of stdout and stderr of the node.exe process, consider using debugging and ETW traces to further diagnose the problem.

The last 64k of the output generated by the node.exe process to stderr is shown below:

(node:3256) [DEP0005] DeprecationWarning: Buffer() is d
(Use `node --trace-deprecation ...` to show where the w
Application has thrown an uncaught exception and is ter
Error: source is not a string
 at Object.module.exports [as parse] (\\axisfiles.aw
 at \\axisfiles.aws.axisgis.com\share\axisapi\_prod\A

Click To Open AxisGIS Maps

Neighborhood 3 Yard Item(s) Size Year Quantity Description 16000 1968 PAVING ASPHALT



Search Home

Previous Print

Next

Disclaimer: This information is for tax assessing purposes and is not warranted

#### **Parcel Identification**

0013-031.000 545

Account 73 - Ex Charter State Code

Card 1/1

Map/Lot

40-0040-00 User Account

#### **Assessment**

\$102,600 Land Building \$453,800 Card Total \$556,400 Parcel Total \$556,400

# **Prior Assessments**

Fiscal Year	Land Value	<b>Building Value</b>	Outbuilding Value	Total Value
2024	\$102,600	\$445,600	\$8,200	\$556,400
2023	\$102,600	\$445,600	\$8,200	\$556,400
2022	\$85,500	\$419,200	\$8,200	\$512,900
2021	\$85,500	\$419,200	\$8,200	\$512,900
2020	\$85,500	\$419,200	\$8,200	\$512,900

## **Location and Owner**

Location

1 BESTWICK TRL

Owner Owner2 HOPKINS HILL RD FIRE DEPT

Owner3

1 BESTWICK TR Address

Address2

COVENTRY RI 02816 Address3

# **Building Information**

Design Year Built

Heat

FireStns 1953 FWA w/AC 0

Fireplaces Rooms **Bedrooms** 

0 0

2 Full Bath\ 1 Half Bath Bathrooms

3,888 SF Above Grade Living Area


#### Sale Information

Sale Date Sale Price 09/27/1988 \$0

Legal Reference 76-402

Instrument





# **Building Sub Areas**

Sub Area	Net Area
1st FLOOR	540 SF
GARAGE	2,100 SF
HALF STORY	1,116 SF
OFFICE AREA	2,232 SF
OPEN PORCH	117 SF
WOOD DECK	180 SF

HRESULT: 0x6d HTTP status: 500 HTTP subStatus: 1013

HTTP reason: Internal Server Error

You are receiving this HTTP 200 response because system.webServer/iisnode/@devErrorsEnabled configuration setting is 'true'.

In addition to the log of stdout and stderr of the node.exe process, consider using  $\underline{\text{debugging}}$  and  $\underline{\text{ETW traces}}$  to further diagnose the problem.

The last 64k of the output generated by the node.exe process to stderr is shown below:

(node:5188) [DEP0005] DeprecationWarning: Buffer() is d
(Use `node --trace-deprecation ...` to show where the w
Application has thrown an uncaught exception and is ter
Error: source is not a string
 at Object.module.exports [as parse] (\\axisfiles.aw
 at \\axisfiles.aws.axisgis.com\share\axisapi\_prod\A

Click To Open AxisGIS Maps

#### **Land Information**

Land Area

0.19 AC

Zoning

R-20

Fire District

Hopkins Hill - (401) 821-1989

Neighborhood

# Yard Item(s)

Description

Quantity

Size Year

PAVING ASPHALT

4000 1968





Home

Search

Print

Previous

Next

Disclaimer: This information is for tax assessing purposes and is not warranted

#### **Parcel Identification**

0013-032.000

Account State Code

Map/Lot

546 73 - Ex Charter

Card 1/1 User Account

40-0040-01

#### Assessment

\$151,200 Land Building \$57,700 Card Total \$208,900 \$208,900 Parcel Total

#### **Prior Assessments**

Fiscal Year	Land Value	<b>Building Value</b>	Outbuilding Value	Total Value
2024	\$151,200	\$51,800	\$5,900	\$208,900
2023	\$151,200	\$51,800	\$5,900	\$208,900
2022	\$126,000	\$47,900	\$6,100	\$180,000
2021	\$126,000	\$47,900	\$6,100	\$180,000
2020	\$126,000	\$47,900	\$6,100	\$180,000

## **Location and Owner**

Location

0 HOPKINS HILL RD

Owner

HOPKINS HILL RD FIRE DEPT

Owner2 Owner3

Address

1 BESTWICK TR

Address2

Address3

COVENTRY RI 02816

# **Building Information**

Design Year Built

Heat

Fireplaces

Rooms

**Bedrooms** 

Bathrooms

Above Grade Living Area

Gar Rpr 1998

Forced Air

0

2 Half Bath

1,036 SF

# **Sale Information**

Sale Date 08/06/1982 Sale Price \$0

Legal Reference 142-676

Instrument

# **Building Sub Areas**

Sub Area

1st FLOOR

**Net Area** 

1,036 SF


# **Land Information**

Land Area Fire District 0.28 AC

Zoning

R-20 Hopkins Hill - (401) 821-1989

DISA



37

HRESULT: 0x6d HTTP status: 500 HTTP subStatus: 1013 HTTP reason: Internal Server Error

You are receiving this HTTP 200 response because system.webServer/iisnode/@devErrorsEnabled configuration setting is 'true'.

In addition to the log of stdout and stderr of the node.exe process, consider using debugging and ETW traces to further diagnose the problem.

The last 64k of the output generated by the node.exe process to stderr is shown below:

(node:9508) [DEP0005] DeprecationWarning: Buffer() is d (Use `node --trace-deprecation ...` to show where the w Application thrown an uncaught exception and is ter Error: source is not a string

at Object.module.exports [as parse] (\\axisfiles.aw at \\axisfiles.aws.axisgis.com\share\axisapi\_prod\A

Click To Open AxisGIS Maps

	Yard Item(s)		
Description	Quantity	Size	Year
PAVING ASPHALT	1	2000	1998

Neighborhood





Home

Search

Print

Previous

Next

Disclaimer: This information is for tax assessing purposes and is not warranted

#### **Parcel Identification**

0055-038.000 5625

73 - Ex Charter State Code 1/1

Card

Map/Lot

Account

40-0020-00 User Account

#### **Assessment**

\$177,600 Land \$821,400 Building Card Total \$999,000 Parcel Total \$999,000

#### **Prior Assessments**

Value
,000
,000
,800
,800
,800

## **Location and Owner**

Location Owner

571 WASHINGTON ST COVENTRY FIRE DISTRICT ANTHONY FIRE STATION

571 WASHINGTON ST

Owner2

Owner3

Address Address2

COVENTRY RI 02816 Address3

# **Building Information**

Design Year Built Heat

FireStns 1925 FWA w/AC 0


Fireplaces Rooms **Bedrooms** 


1 Full Bath\ 2 Half Bath Bathrooms

Above Grade Living Area

8,627 SF

ng Value	Outbuilding Value	Total Value
.00	\$30,000	\$999,000
00	\$30,000	\$999,000
00	\$28,700	\$872,800
00	\$28,700	\$872,800





# Sale Information

# **Building Sub Areas**

Sub Area 1st FLOOR 2nd FLOOR 3rd FLOOR

**Net Area** 5,523 SF 2,704 SF 400 SF

# **Land Information**

Land Area

0.37 AC



HRESULT: 0x6d HTTP status: 500 HTTP subStatus: 1013

HTTP reason: Internal Server Error

You are receiving this HTTP 200 response because <u>system.webServer/iisnode/@.devErrorsEnabled</u> configuration setting is 'true'.

In addition to the log of stdout and stderr of the node.exe process, consider using  $\underline{\text{debugging}}$  and  $\underline{\text{ETW traces}}$  to further diagnose the problem.

The last 64k of the output generated by the node.exe process to stderr is shown below:

(node:8992) [DEP0005] DeprecationWarning: Buffer() is d (Use `node --trace-deprecation ... to show where the w Application has thrown an uncaught exception and is ter Error: source is not a string

at Object.module.exports [as parse] (\\axisfiles.aw at \\axisfiles.aws.axisgis.com\share\axisapi\_prod\A

Click To Open AxisGIS Maps

Zoning Fire District Neighborhood

Coventry (Anthony) - (401) 821-3141

3

Yard Item(s)





Home

Search

Print

Previous

Next

Disclaimer: This information is for tax assessing purposes and is not warranted

# **Parcel Identification**

0316-059.007

11230 Account State Code 73 - Ex Charter

Card

Map/Lot

40-0060-00 User Account

#### **Assessment**

Land \$817,900 \$1,145,500 Building Card Total \$1,963,400 \$1,963,400 Parcel Total

# **Prior Assessments**

Fiscal Year	Land Value	<b>Building Value</b>	Outbuilding Value	Total Value
2024	\$817,900	\$1,122,400	\$23,100	\$1,963,400
2023	\$817,900	\$1,122,400	\$23,100	\$1,963,400
2022	\$681,600	\$1,025,000	\$39,800	\$1,746,400
2021	\$681,600	\$1,025,000	\$39,800	\$1,746,400
2020	\$681,600	\$1,025,000	\$39,800	\$1,746,400

#### **Location and Owner**

Location

1110 VICTORY HWY

Owner

WESTERN COVENTRY FIRE DISTRICT

Owner2

Owner3 Address

1110 VICTORY HIGHWAY

Address2

GREENE RI 02827 Address3

# **Building Information**

Design

Year Built

Heat Fireplaces

Rooms

Bedrooms

**Bathrooms** 

0

0

3 Full Bath\ 2 Half Bath

Above Grade Living Area

8,260 SF

FireStns

FWA w/AC

2008

#### Sale Information


784-126

Sale Date 03/19/1999 Sale Price \$126,000

Legal Reference

Instrument





# **Building Sub Areas**

Sub Area

1st FLOOR

MEZZANINE - STORAGE OPEN PORCH

**Net Area** 

8,260 SF

352 SF

40 SF

#### **Land Information**

Land Area

6.02 AC

HRESULT: 0x6d HTTP status: 500 HTTP subStatus: 1013

HTTP reason: Internal Server Error

You are receiving this HTTP 200 response because system.webServer/iisnode/@devErrorsEnabled configuration setting is 'true'.

In addition to the log of stdout and stderr of the node.exe process, consider using <u>debugging</u> and <u>ETW traces</u> to further diagnose the problem.

The last 64k of the output generated by the node.exe process to stderr is shown below:

(node:8488) [DEP0005] DeprecationWarning: Buffer() is d (Use `node --trace-deprecation ...` to show where the w Application has thrown an uncaught exception and is ter Error: source is not a string
at Object.module.exports [as parse] (\\axisfiles.aw

at \\axisfiles.aws.axisgis.com\share\axisapi\_prod\A

Click To Open AxisGIS Maps

Zoning

R-3A

Fire District Neighborhood Western Coventry - (401) 397-5916

# Yard Item(s)

Description	Quantity	Size	Year
PAVING ASPHALT	1	10000	2008
SIGN W/INTERIOR LIGHTS	2	32	2008



Home

Search

**Assessment** 

Print

Previous

Next

Disclaimer. This information is for tax assessing purposes and is not warranted

# **Parcel Identification**

0314-048.000

Account 10993 State Code 73 - Ex Charter

Card 1/1

User Account

Map/Lot

40-0060-00

3 Building

 Land
 \$137,800

 Building
 \$246,500

 Card Total
 \$384,300

 Parcel Total
 \$384,300

## **Prior Assessments**

Fiscal Year	Land Value	<b>Building Value</b>	Outbuilding Value	Total Value
2024	\$137,800	\$231,500	\$15,000	\$384,300
2023	\$137,800	\$231,500	\$15,000	\$384,300
2022	\$113,200	\$202,800	\$14,100	\$330,100
2021	\$113,200	\$202,800	\$14,100	\$330,100
2020	\$113,200	\$202,800	\$14,100	\$330,100

#### **Location and Owner**

Location

2 HOPKINS HOLLOW RD

Owner Owner2 WESTERN COVENTRY FIRE DISTRICT

Owner

Owner3 Address

1110 VICTORY HIGHWAY

Address2

Address3

Above Grade Living Area

GREENE RI 02827

# **Building Information**

 Design
 FireStns

 Year Built
 1940

 Heat
 Forced Air

 Fireplaces
 0


 Rooms
 0


 Bedrooms
 0

 Bathrooms
 1 Half Bath

# Sale Information

2,048 SF





# **Building Sub Areas**

Sub Area 1st FLOOR Net Area 2,048 SF

# Land Information

Land Area

0.96 AC

Zoning

R-5A

Fire District

Western Coventry - (401) 397-5916

HRESULT: 0x6d HTTP status: 500 HTTP subStatus: 1013 HTTP reason: Internal Server Error

You are receiving this HTTP 200 response because system.webServer/iisnode/@devErrorsEnabled configuration setting is 'true'.

In addition to the log of stdout and stderr of the node.exe process, consider using debugging and ETW traces to further diagnose the problem.

The last 64k of the output generated by the node.exe process to stderr is shown below:

(node:4504) [DEP0005] DeprecationWarning: Buffer() is d (Use `node --trace-deprecation ... ` to show where the w Application has thrown an uncaught exception and is ter

Error: source is not a string
at Object.module.exports [as parse] (\axisfiles.aw
at \\axisfiles.aws.axisgis.com\share\axisapi\_prod\A

Click To Open AxisGIS Maps

Neighborhood

Description

PAVING ASPHALT

**GARAGE** 

4

Yard Item(s) Size Year Quantity 540 1968 1940 2400 1